

Visit Report Sheet

<p style="text-align: right;">C1027</p> <p>AIG Control Systems Ltd Otter Pool Barn West Stowford Barton Barn, West Stowford, Ilfracombe Devon, England EX34 8PJ</p> <p>07970 538998</p>	<p style="text-align: center;">Visit Details</p> <p>Visit Type: Service Order No: 1376/ Date/Time: 04/03/2025 15:24 Time Completed: 15:39</p>
<p>Job Details</p> <p>Service due,</p>	<p style="text-align: center;">Lift Details</p> <p>Asset /Location: Ground Floor Bedroom Make: OpeMed Model: Elite 2 Compact Serial: 17160734 S.W.L. 200kg Installed:</p>
<p>Completion Notes</p> <p>Upon arrival, the bedroom/ensuite's gated double XY ceiling track hoist was found to be off charge. However, the batteries appear to be in good order and are currently accepting a charge, indicating no fundamental issue with the battery system itself. Inspection passed.</p> <p>Parts Used</p>	<p style="text-align: center;">Further Work Required</p>

VAT Exemption Certificate - Eligibility declaration by an individual

I declare that i am chronically sick or disabled and suffering from _

I am receiving a qualifying Product or Service/Maintenance visit supplied to me for my domestic or personal use. I claim relief from Value Added Tax under group 12 of schedule 8 of the Value Added Tax Act 1994. The work has been completed.

Customer Name: AIG Control Systems Ltd

Customer Sign:

Date: 04/03/2025

Rep Name: Mark Pringle

Rep Sign: 

Date: 04/03/2025



Service Checks

Customer

C1027

AIG Control Systems Ltd
Otter Pool Barn
West Stowford Barton Barn,
West Stowford,
Ilfracombe
Devon, England
EX34 8PJ

Visit Details

Visit Code: J1376
Order No: TVMC/04/03/2025
Consultant: Same As Site

Make: OpeMed
Model: Elite 2 Compact
Serial: 17160734

Equipment Examined

Check Item	Status	Remarks
EIN number if present/Asset Number	N/A	
What is S.W.L. (Kg)?	Pass	200kg
Track & track fixings	Pass	
Is SWL sticker showing on tracking?	Pass	
Ancillary fixings	Pass	
Up and down control	Pass	
Traverse motor if fitted	Pass	
Lifting gear & OSG	Pass	
Motor mounting bolts	Pass	
Motor gearbox leaks	N/A	
Lifting spool & tape retaining pin	Pass	
Condition of lifting tape	Pass	
Date lift tape last changed (Transactive)	N/A	
Spreader bar & tape retaining mechanism	Pass	
Traverse rollers	Pass	
Check room covering trolleys & fixings if fitted	Pass	
Abnormal noise or resistance	Pass	
Lubricate where necessary	N/A	
Low voltage wiring	Pass	
Mains wiring to charger	Pass	
Motor brushes if applicable	N/A	
Battery test 1 readings in v & Ah- Serial Number of Battery	Pass	12.56V 2.1Ah
Battery test 2 readings in v & Ah- Serial Number of Battery	Pass	12.76V 2.2Ah
Auxiliary emergency lowering battery reading v- Serial Number of Battery	N/A	
Charger test readings v	Pass	27V DC
Up limit switch	Pass	
Final up limit switch	Pass	
Down limit switch	Pass	
Reverse wind / slack tape switch	Pass	

Split Pins in Carrier Trolley (Robin CTH)	N/A	
Emergency stop switch	Pass	
Is emergency lowering key present if applicable	N/A	
Emergency lowering function manual	N/A	
Emergency lowering function electric	Pass	
Controlled emergency lowering function	Pass	
Hoist cover and head protection cover	Pass	
Sling Inspection	N/A	
User instructions present	Pass	
Labelling inc SWL & contact numbers	N/A	
Weight Test if applicable	N/A	

Consent Request

Check Item	Status	Remarks
Does client give consent for any pictures taken to be used on social media?	N/A	

Rep Name: Mark Pringle

Rep Sign: 

Date: 04/03/2025

